

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 31 Township: 7N Range: 2E

Corner ID: Polk c- 25


Monument Description & Remarks: 3" aluminum cap "T7N R2E 1/4 S 31 1986 SO336"

References On File: Survey by Ken Anderson, Recorder's book 3 page 286.


Field Book: 2000-02

Page No.: 30

USGS Quad: Norman



Tie Sheet Drawing
(Not to Scale)



A-3" aluminum disc.

B-N 33 ° E 8.13' to MAG nail in 28" black oak.

C-S 90 ° E 34.09' to MAG nail in 12" sugar maple.

D-S 09 ° W 25.19' to MAG nail in sugar maple. Survey Marker 6' A.G.

E-N 85 ° W 151.50' to sandstone with "X".

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code; and the above data is given under my hand this 3rd day of October, 2000.

Kevin P. Enright

Certified and sealed by the Monroe County Surveyor Review Board

Date: *December 14, 2000*



November 28, 2000


Index No. 2-3
(alphabetical-numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-6660-11 10/15/81

T. 7N R. 2E 2nd Mer. N.F. Hoosier County Monroe State Indiana
S 4 Corner common to sections 31 and _____

EXISTING SURVEYS	
<p>Original Government Survey</p> <p>Year surveyed <u>1811</u></p> <p>Original monument <u>Wood Post</u> <small>(Wood post, stone, pile of stones, post, etc.)</small></p> <p>Bearing Trees</p> <p>Species <u>Hickory</u> <u>Hickory</u></p> <p>Diameter <u>7"</u> <u>7"</u></p> <p>Bearing <u>S 55 W</u> <u>N 63 E</u></p> <p>Distance <u>25'</u> <u>31'</u></p>	<p>Original Evidence Found</p> <p>Year of search <u>1986</u> by <u>V.H.M.</u></p> <p>Monument found <u>None</u></p> <p>Original Bearing Trees Found</p> <p>Species <u>None</u> <u>h"</u></p> <p>Diameter _____</p> <p>Bearing _____</p> <p>Distance _____</p>
<p>Subsequent Corner Restoration</p> <p>Year surveyed _____ By _____</p> <p>Where filed or recorded _____</p> <p>Monument <u>No records recovered for this corner</u> <small>(Original, concrete post, iron rod, etc.)</small></p> <p>Bearing Trees, Reference Objects</p> <p>Species _____</p> <p>Diameter _____</p> <p>Bearing _____</p> <p>Distance _____</p>	<p>Evidence of Subsequent Corner Restoration Found</p> <p>Year of search <u>1986</u> By <u>V.H.M., R.A.G. & R.C.E.</u></p> <p><u>None</u></p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p>



Sketch
O Corner ☒ F.S. Land

At time of search:

1. Did you have the record description?
Yes X No _____

2. How was search area located?
Pacing, chaining, photos, maps,
etc. chaining

3. Man hours spent in search 2

4. Do you think additional search might
recover evidence? Yes _____ No X

5. Signature Victor B. McCarty

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. Corner is situated on west face of slope, 70'± south of drainage flowing west, 250'± west of northwest corner of planted pine area.

Perpetuation Record

Monument and accessories established. Include brief description of area. Set 30" aluminum monument stamped to identify corner.

Accessories established:

Sugar Maple	Sugar Maple
12"	9"
S 03 W	N 89 E
25.6'	34.7'

Certified corner restoration certificate prepared: Yes _____ No _____
Filed in county records at _____ Date _____ County Document No. _____
Identified on aerial photo No. _____ Which is filed at _____

Index No. 2-3
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO: 802-127T. 7 N R. R2E 2nd Mer. N.F. Harsier County Monroe State Indiana
S 14 Corner common to sections 31 and _____

EXISTING SURVEYS	
Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ (Wood post, stone, pile of stones, pipe, etc.)	Monument found _____
S D B D	Original Bearing Trees Found


Y W M — — — —	Subsequent Corner Restoration Found

S D B D	Bearing Trees, Reference Objects

The corner via McCawley
Set S 1/4 Sec 31 and
the stone M. Hilderbrand
found are two different
corners. 8-19-91 *th*

Index No. 2-3
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO: 802-127T. 7 N R. R2E 2nd Mer. N.F. Harsier County Monroe State Indiana
S 14 Corner common to sections 31 and _____

EXISTING SURVEYS	
Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ (Wood post, stone, pile of stones, pipe, etc.)	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____	Year of search <u>11-6-1985</u> By <u>Mike Hilderbrand</u>
Where filed or recorded _____	<u>Recovered sandstone 3" x 6" extends</u>
Monument _____ (Original, concrete post, iron rod, etc.)	<u>7" above ground level. Approx 8"</u>
_____	<u>in ground. Lose and leaning to the</u>
_____	<u>West. Has (+) on top of stone. No</u>
_____	<u>scribing</u>
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____



Sketch
☐ Corner ☒ F.S. Land

At time of search:

1. Did you have the record description?
 Yes ☒ No ☐

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc.

3. Man hours spent in search 15 min

4. Do you think additional search might
 recover evidence? Yes ☒ No ☐

5. Signature Mike H. Hahn

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. Stone is located on west facing slope. Drainage approx 40 feet west running south-west. Tree line running East and South

Perpetuation Record

Monument and accessories established. Include brief description of area.

Establish following Bearing Trees

B. Oak

W. Oak

9'

14'

S 44° W

N 62° W


6.50 feet

14.40 feet

Certified corner restoration certificate prepared: Yes ☐ No ☐

Filed in county records of _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____



Sketch
☐ Corner ☒ F.S. Land

At time of search:

1. Did you have the record description?
 Yes ☒ No ☐

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. chaining

3. Man hours spent in search 2

4. Do you think additional search might
 recover evidence? Yes ☐ No ☒

5. Signature Vicki H. McCaul

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. Corner is situated on the north face of slope approximately 300' north of northwest corner of clearing. 30'± south of east-west drainage on steep slope. Finger drains to west 15' and east 30'±.

Perpetuation Record

Monument and accessories established. Include brief description of area. Set 30" aluminum monument stamped to identify corner.

Accessories Established

Beech

Sugar Maple

4"

8"

S 75 E

North

13.6'

2.2'

Certified corner restoration certificate prepared: Yes ☐ No ☐

Filed in county records of _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____